

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

IU1238
North
> 1
1.603 mi.
8463 ft.

MANHOLE#38173
WEST 6TH/HIGHLOWN AVE
BROOKLYN, NY

NY Spills S106970540
N/A

Site 2 of 2 in cluster IU

Relative:
Higher

Actual:
20 ft.

SPILLS:

Name: MANHOLE#38173
Address: WEST 6TH/HIGHLOWN AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0505821 / 2008-08-27
Facility ID: 0505821
Facility Type: ER
DER Facility ID: 297920
Site ID: 350919
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 2401
Spill Date: 2005-08-11
Investigator: SKARAKHA
Referred To: Not reported
Reported to Dept: 2005-08-11
CID: 444
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2005-08-11
Spill Record Last Update: 2008-08-27
Spiller Name: ERT DESK'
Spiller Company: MANHOLE#38173
Spiller Address: WEST 6TH/HIGHLOWN AVE
Spiller Company: 001
Contact Name: ERT DESK'
DEC Memo: "08/27/08 - See eDocs for Con Ed report detailing cleanup and closure. 160429. 8-11-05 14:10 HRS. R. TUCKER 12264 (#9) REPORTS, 1/2 OZ OF DIELECTRIC OIL LEAKED ONTO SOLID CEMENT FLOOR IN MH38173. AT THIS TIME OIL APPEARS TO BE CONTAINED AND NO SEWERS OR WATERWAYS WERE AFFECTED. OIL WAS DISCOVERED WHEN #9 WAS CALLED TO DETERMINE IF THE JOINT WAS LEAKING. JOINT WAS CONFIRMED TO BE LEAKING AND D- FAULTED WITH TAG# 2383. AT THIS TIME NO SAMPLE CAN BE TAKEN UNTIL FEEDER COMES OFF,. FEEDER WONT BE COMMING OFF FOR AT LEAST THREE DAYS. ENV STOP TAG# 39007 WAS PLACED. DIAPERS WERE PLACED, NO FIRE, SMOKE OR PRIVATE PROPERTY WAS NOTICED AND NO INJURIES WERE RELATED TO SPILL WITH NO WEATHER CONDITIONS CONTRIBUTING TO THE HAZARD OF THE SPILL. CLEANUP PENDING SAMPLE RESULTS. S. PACE 49874. "

Remarks: "NO TO 5 QUESTIONS: CONED # 160429"

All Materials:

Site ID: 350919
Operable Unit ID: 1108458
Operable Unit: 01
Material ID: 2098398
Material Code: 0541A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported